## MA. ERIAL SAFETY DATA S. EET DPM 1112-A

"Essentially Similar" to U. S. Department of Labor Form LSB-OOS-4

SECTION 1 IDENTIFICATION OF PRODUC	
Manufacturer's NAME McGean Chemical Co., Inc.	EMERGENCY TELEPHONE NO. 213/861 12
ADDRESS 9520 E. CeeBee Drive, Downey, CA 90241	
TRADE NAME AND SYNONYMS  CEE-BEE B-6	
CHEMICAL NAME AND SYNONYMS  aluminum oxidation and corresi	on remover
CHEMICAL FAMILY COMPOUND MOLECULAR FORMULA	blend

COMPONENT	%	THRESHOLD LIMIT VALUE	сом	PONENT	*	THRESHOLD LIMIT VALUE
		(UNITS)				(UNITS)
Hydrofluoric acid; less than	1	3	ppm			
Phosphoric acid; less than	5					
Isopropanol alcohol;	10-1	5 400	ppm (skin)			

OILING POINT (°F.)	190	SPECIFIC GRAVITY (H2O=1)		1.03
APOR PRESSURE (mm Hg.)	23	PERCENT VOLATILE BY VOLUME (%)		78
APOR DENSITY (AIR=1) same as	water	EVAPORATION RATE (	same as	water
OLUBILITY IN WATER	complete	•		

LASH POINT none up to and initial boiling	point	FLAMMABLE LIMITS (PERCENT BY VOLUME)	non-flammabl	
IRE-EXTINGUISHING MEDIA	n/a			
PECIAL FIRE-FIGHTING PROCEDURES	n/a			

## SECTION Y HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE

vapors non-toxic

EFFECTS OF OVEREXPOSURE

Severe irritant to skin and eyes

EMERGENCY AND FIRST AID PROCEDURES

For eye contact, flush thoroughly with water/immediately seek medical attention.

For skin contact, wash thoroughly with soap and water.

STABILITY	UNSTABLE	CONDITIONS TO AVOID
SIABILIT	STABLE	
INCOMPATIBILITY (A	laterials to avoid)	caustic materials
HAZARDOUS DECOM	APOSITION PRODUCTS,	
HAZARDOUS POLYMERIZATION	MAY OCCUR	CONDITIONS TO AVOID
	WILL NOT OCCUR	· · · · · · · · · · · · · · · · · · ·

## SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

treat with lime and flush away with water

WASTE DISPOSAL METHOD

treat with lime, dilute with water and release to sewer

. <b>539</b> , t3.	SECTION VIII SPECIAL PR					
RESPIRATORY PROTE	CTION (Specify type) none required					
	LOCAL EXHAUST		SPECIAL			
VENTILATION	MECHANICAL (General)		OTHER			
PROTECTIVE GLOVES	acid resistant	EYE PRO		ace shield		
OTHER PROTECTION EQUIPMENT wash rack gear						

## SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Avoid damage to containers. Store @ 32-90°F

OTHER PRECAUTIONS

Do not contain in galvanized container